

FIG. 14A




FIG. 14B

Test Run 7 (6-12) – No Flash Detected




FIG. 15

Exhaust Flash
6-12 Test Run 8




FIG. 16A

Exhaust Flash
6-12 Test Run 8




FIG. 16B




FIG. 17




FIG. 18A




FIG. 18B




FIG. 19A




FIG. 19B

Exhaust Flash
6-13 Test Run 1




FIG. 20A

Exhaust Flash
6-13 Test Run 1




FIG. 20B




FIG. 21A




FIG. 21B




FIG. 22A




FIG. 22B




FIG. 23A




FIG. 23B




FIG. 24A




FIG. 24B




FIG. 25A




FIG. 25B




FIG. 26